

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1284	250/342	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:26
L2	1571	250/330	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:26
L3	3	250/341.1 and defect and camera and sound and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:27
L4	2	L1 and defect and camera and sound and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:27
L5	3	L2 and defect and camera and sound and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:27
L6	3	L3 and defect and camera and sound and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:32
L8	16	L1 and defect and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:27
L9	29	L2 and defect and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:27
L10	3	L3 and defect and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L11	216	250/341.6	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L12	17	L11 and defect and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L13	9	VIBROTHERMOGRAPH\$	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:31

L14	0	L1 and L13	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L15	3	L2 and L13	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L16	0	L3 and L13	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L17	5	L11 and L13	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
L18	9	250/334 and defect and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:31
L19	5	VIBROTHERMOGRAPH\$ and coupl\$4 same transduc\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:31
L21	3	L3 and defect and (vibrat\$4 or acoust\$4)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:33
L22	45	L2 and defect and (vibrat\$4 or acoust\$4)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:33
L23	19	L1 and defect and (vibrat\$4 or acoust\$4)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:33
L24	27	L11 and defect and (vibrat\$4 or acoust\$4)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:33
L25	21	250/334 and defect and (vibrat\$4 or acoust\$4)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:33
S1	216	250/341.6	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:26

S2	6	"6232701"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:21
S3	25	"6236049"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:21
S4	5	"6274967"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:21
S5	10	"6399948"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:22
S6	5	"6437334"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:22
S7	8	"6593574"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:22
S8	8	"3599477"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:22
S9	23	"3756071"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:23
S10	11	"3861200"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:23
S11	10	"4174635"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:23
S12	18	"4607341"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:23
S13	12	"5461921"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:24

S14	13	"5493511"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:24
S15	2	"5633468"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:25
S16	11	"5763786"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:25
S17	2	"6622560"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:25
S18	2	"20020121602"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:26
S19	2	"20020172410"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:26
S20	2	"20030010124"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:26
S21	2	"20030106376"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:26
S22	2	"20030115963"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 13:27
S23	56	250/341.6 and defect and camera	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:26
S24	16	("20020018510" "20040114662" "4266185" "4345457" "4557607" "4647220" "4760304" "4826326" "4983836" "5111048" "5302830" "5748003" "5810477" "6236049" "6437334" "RE32166").PN. OR ("6874932").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/05/20 13:44

S25	30	("3934452" "4232554" "4378701" "4463608" "4541059" "4625557" "4710030" "4828400" "4878116" "4950897" "4950990" "5201582" "5201841" "5287183" "5376793" "5417494" "5476010" "5495763" "5748318" "5837896").PN. OR ("6236049").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/05/20 13:48
S26	16	250/341.6 and defect and camera and sound	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 14:11
S27	31	("20020013954" "20020036617" "3934452" "4229658" "4232554" "4378701" "4463608" "4541059" "4607341" "4625557" "4710030" "4782990" "4828400" "4878116" "4950897" "4950990" "4961346" "5137200" "5201582" "5201841" "5287183" "5376793" "5417494" "5476010" "5495763" "5567881" "5748318" "5837896" "6382967").PN. OR ("6593574"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/05/20 14:05
S28	7	250/341.6 and defect and camera and sound and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:27
S29	26	("3934452" "4232554" "4378701" "4463608" "4541059" "4625557" "4710030" "4828400" "4874251" "4878116" "4950897" "4950990" "5201582" "5201841" "5287183" "5376793" "5417494" "5476010" "5495763" "5748318" "5837896" "5853290" "6236049").PN. OR ("6437334"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/05/20 14:13
S30	0	("2004/0089812").URPN.	USPAT	OR	ON	2005/05/20 14:15
S31	4	250/334 and defect and camera and sound and vibrat\$4	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:31

S32	6	250/334 and defect and camera and sound and pulse	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 14:44
S33	9	"VIBROTHERMOGRAPHY"	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 12:28
S34	8	250/334 and defect and camera and sound and (pulse or vibrat\$6)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/20 14:45
S35	9	"VIBROTHERMOGRAPHY" and (defect or crack or surface)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 09:36
S36	5	"VIBROTHERMOGRAPHY" and (defect or crack or surface) and coupler	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:07
S37	1	"VIBROTHERMOGRAPHY" and (defect or crack or surface) and meter	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:09
S38	0	"VIBROTHERMOGRAPHY" and (defect or crack or surface) and vibr\$4 adj meter	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:10
S39	1	"VIBROTHERMOGRAPHY" and (defect or crack or surface) and microphone	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:33
S40	224	VIBRO\$ and (defect or crack or surface) and microphone	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:30
S41	2171	vibrate and (defect or crack or surface) and microphone	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:30
S42	1	250/341.6 and defect and camera and microphone	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:31
S43	79	vibrate and defect and camera and microphone	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:31

S44	50	vibrate and defect and camera and microphone and transducer	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:32
S45	5	vibrate and defect and camera and microphone and transducer and coupler	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:32
S46	1	"VIBROTHERMOGRAPHY" and (defect or crack or surface) and microphone and meter	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2005/05/23 10:33